

Double block & bleed: understanding a barrier - part 5



Norwegian consultant and valve instructor, Ingolf Fra Holmslet, continues his bi-monthly series of informative articles.

ingolf@valve.no
www.valve.no

When preparing for a job to be done most production personnel in the hydrocarbon industry are focused upon the double block & bleed. For a job to be safely done everything has to be in accordance with the company policy which normally, for double block & bleed, is up to the point the job commences. But it is not always that simple, one can end up in a situation like one which I was involved in many years ago.

There was a 36" pipeline valve as illustrated in Figure 22, an ESD export valve on a platform in the Norwegian sector of the North Sea (152 bar gas). The valve was a top entry trunnion mounted ball valve with seats of the self-relief type. It was an in welded valve and there was a major spindle leakage every time the valve was operated.

The leakage stopped around 30 minutes after operation both towards the open and closed positions.

As illustrated in Figure 23 there were no lubricant fittings in the stem seal area and there was one O-ring (green) under the bonnet and one graphite packing (red) above the bonnet under the yellow packing retainer. Preparing for this job there were several facts to consider:

1. There was no balance hole in the ball.
2. There was one vent plug on top of the bonnet, Figure 22.
3. One drain valve was installed at the bottom of the valve, not on the drawing.
4. The seats were of the type SR with soft seals, Figure 24.
5. No lubricant fitting to the stem packings, Figure 23.
6. 400 km to the next valve on the down stream side.

There was no way of getting double block and bleed on the downstream side of the

valve without blowing down a 36" and 400 km long pipeline, or setting a hydraulic plug after the valve. Both alternatives would involve a multi-million project demanding many days of total shut down through that pipeline.

My suggestion in this situation was to replace the graphite packing under the retainer with a specially made O-ring and a spacer to fill in the extra distance between the O-ring and the retainer plate. To keep the ball in balance I suggested doing the job with the valve in its open position. There were a lot of discussions concerning this, as the company felt safer working with the valve in the closed position. But if you look at the valve in Figure 25 you will see that there is no difference between when the valve is in the open or closed position; it will be the same soft seal on the seat making the seal against the ball. The seal force that the system pressure compresses each seat against the ball was calculated to be equivalent to around 35 tons. With the valve in the open position the force from the pressure inside the ball bore was totally balanced. If the valve was in the closed position any reduction in the pressure on the platform side would cause the pipeline pressure to force the ball to one side and possibly create problems re installing the retainer plate. In the worst case scenario any tilting of the ball




Figure 22.




Figure 23.




Figure 24.

could create a leak past the seat/ball seal. By keeping the valve in the open position this problem was avoided. This could be done because the ball was without a balance hole.

The valve was operated to its open position, but the production on the installation was stopped as this made the HMS personnel feel safer. But it did not matter as the downstream side of the valve was filled with trillions m³ of gas; it's all in the head. After 30 minutes the bleed plug was opened, left open for 15 minutes and the valve did have a small leakage that could be measured close to the bleed plug, but not in a 10 cm distance. Both seats sealed perfectly towards the ball but there were some small scratches on the soft seal of one or both of the seats. The drain plug was closed and the bottom drain valve opened.

Now the actuator was disconnected and removed. There was no increase in the leak rate out of the drain valve. The retainer plate was removed and the graphite packing taken out of the groove. A new O-ring and spacer had already




Figure 25.

been produced, so the packing groove was cleaned, lubricated and the O-ring was installed with the spacer on top as illustrated in Figure 26. After installation of the retainer the cavity was slowly pressurized with N₂ up to production pressure of 152 bar. The O-ring was tested with Snoop[®] and not a bubble registered.

It took me 20 minutes from when I started removing the retainer plate until it was back in place with a new O-ring. After the O-ring was tested and accepted there came a comment from the platform manager:




Figure 26.

"Was that all?" I had to answer: *"Yes that was it."*

That was a perfectly safe operation, but not in accordance with the company policy of double block & bleed. As I have stated earlier: It's all in the head, you need to have personnel that know how valves work and how to maintain them in a safe way. Sometimes the struggle for double block & bleed makes the operation more dangerous. The most important issue is to do it SAFELY.

To be continued...